


## Trim and corner-squareness test

One-sided cutting test / Rectangle 140 x 150 mm / Not a certified measuring tool

---



Measure width and height with a known ruler before cutting. Do not compensate for a scaled print by moving the trim.

Cut on the outer solid rectangle; the dashed diagonals are measurement guides, not cut lines.

Measure both diagonals and inspect the corners. Unequal diagonals suggest an off-square trim or distorted print. Record the result and repeat before adjusting the printer.